


Installation Guidelines

NOVADISPLAY®
INNOVATIVE DISPLAY SOLUTIONS


3mm Cable Display Systems

800.753.9688 • www.novadisplay.com







Glass Shelving Fixing - CS01-3 Support Installation

- 1) Mark cable positions on floor area. Lay shelves on floor, and mark cable positions, or use measurements below (fig 1).




- 2) With the use of a plumb line, mark and fix cables to ceiling (ensuring that fixings are secure).
- 3) Install cables as per "Cable Fitting Instructions" for CA4-3 supplied.
- 4) Shelf fitting - As a guideline, the lowest shelf should be fixed approx. 24" from the floor, and subsequent shelves approx 12" apart.
- 5) Fix four shelf supports (CS01-3) on center of four cables (see fig 2), and then attach shelf. Adjust shelf to a horizontal position; preferably with a spirit level. Repeat procedure for other shelves.




INSTALLATION TIPS


Concrete




Wood



Lathe & Plaster



Plasterboard



Suspended Ceiling

